




S.R. 26
PLANNING STUDY
SUSSEX COUNTY, DELAWARE
EXISTING CONDITIONS


FIGURE 2E: HISTORIC RESOURCES
LOCATION MAP





 NATIONAL REGISTER LISTED RESOURCE

 NATIONAL REGISTER ELIGIBLE RESOURCE
(50 YEARS OLD OR OLDER) PER THE
HISTORIC RESOURCES SURVEY/
DETERMINATION OF ELIGIBILITY
REPORT, DECEMBER 2003

 PROPERTY 50 YEARS OR OLDER
NOT PREVIOUSLY SURVEYED
NOT ELIGIBLE PER THE
HISTORIC RESOURCES SURVEY/
DETERMINATION OF ELIGIBILITY
REPORT, DECEMBER 2003

 PREVIOUSLY SURVEYED PER THE
APRIL 1999 ARCHITECTURAL
RESOURCE SURVEY BRIDGES 526
AND 527 NEAR MILLSBORO AND
INTERSECTION OF STATE ROUTE 26 AND
STATE ROUTE 17 NEAR MILLVILLE BY
LOUIS BERGER & ASSOC., INC.;
DETERMINED NOT ELIGIBLE

 PREVIOUSLY SURVEYED RESOURCE
(CRS-10 UPDATE FORM PROVIDED)
NOT ELIGIBLE PER THE
HISTORIC RESOURCES SURVEY/
DETERMINATION OF ELIGIBILITY
REPORT, DECEMBER 2003

 DEMOLISHED BUILDING, PER
FIELD SURVEY MARCH 2002
& JULY 2003



SCALE: 1" = 200'

DECEMBER 2003